

## BNC COMPRESSION CONNECTOR FOR MINIATURE COAX PRODUCT LINE

1. Strip the cable 1/4" conductor exposed, and 1/4" dielectric exposed using the TL-CSST stripping tool.

2. Push the braid back over the jacket, place the center pin on the center conductor

3. Push the inner dielectric sleeve over the center pin.

4. Push the inner Connector body over the center pin and dielectric sleeve

5. Push the compression body over the inner connector body and cable. Place the connector into the TL-SNSA Compression Tool. Compress the connector.



CONNECTOR	CONDUCTOR	INSULATION O.D.	CABLE O.D	CABLES
CN-CSBNC-26	26 AWG.	.073"	.108"	WP258263, WP258265

2833 West Chestnut Street  
 Washington, Pa 15301  
 724-222-7060 • Fax: 724-222-6420  
 800-245-4964  
[www.westpenn-cdt.com](http://www.westpenn-cdt.com)